

Information

MOTOR MOUNT NOTE

- 1) An additional ¼" spacer must be inserted between the two lower motor mount attachment points in the cage. This spacer is to be removed if floats are mounted to your GlaStar.
- 2) These motor mounts have been manufactured to close tolerances. It is possible however; that during your mounting process a misalignment of the bolt-holes in the cage occurs. This has been an ongoing problem with SHAI produced cages.
- 3) Apply necessary force to align the bolt-holes.

For your convenience, here is a list of the required hardware.

Four (4)	AN7-44
Four (4)	AN310-7
Four (4)	Barry Mount #94011-20
	Or
Four (4)	Lord Mount #9313-40